2521/105 2601/106 ELECTRICAL MEASUREMENTS AND ANALOGUE ELECTRONICS Oct./Nov. 2011

Time: 3 hours



THE KENYA NATIONAL EXAMINATIONS COUNCIL

DIPLOMA IN ELECTRICAL AND ELECTRONICS ENGINEERING (POWER OPTION) MODULE I

ELECTRICAL MEASUREMENTS AND ANALOGUE ELECTRONICS

3 hours

INSTRUCTIONS TO CANDIDATES

You should have the following for this examination.

Answer booklet;
Drawing instruments;
Scientific calculator/mathematical tables.

This paper consists of **TWO** sections **A** and **B**.

Answer any **THREE** questions from section **A** and **TWO** questions from section **B**.

All questions carry equal marks.

Maximum marks for each part of a question are as shown.

This paper consists of 5 printed pages.

Candidates should check the question paper to ascertain that all the pages are printed as indicated and that no questions are missing.

SECTION A

Answer any THREE questions from this section.

1 .	(a)	State the SI unit of measure for the following quantities:			
			Length;		

(iii) Volume; (iv) Mass. (2 marks)

(b) Describe the following types of instrumental errors:



A voltmeter having a sensitivity of 1000Ω/V reads 100V on its 150V scale (c) (i) when connected across an unknown resistor in series with a milliammeter. Apparent resistance of the unknown resistor;

Actual resistance of the unknown resistor;

Error due to the loading effect of the voltmeter If the milliammeter reads 5mA, determine:

II.

III.

1 A - act = 20-23 Mo. The value of unknown resistance of a wheatstone bridge is given by: $R_x = \frac{R_2 R_3}{R_1}$. If $R_1 = 100 \pm 0.5\% \Omega$ 5/4

 $R_2 = 1000 \pm 0.5\%\Omega$, and $R_3 = 840 \pm 0.5\%\Omega$, determine:

I — Magnitude of the unknown resistance.

II — Limiting error; for the unknown resistance.

(10 marks)

- (2 marks) 2. State "Hall effect" with reference to magnetism. (a)
 - With the aid of a diagram, explain how a fluxmeter is used to measure flux density (b) (12 marks) and hence derive the flux density equation.
 - With the aid of a circuit diagram, explain how inductance is measured using Maxwell's (c) (6 marks) inductance - capacitance Bridge.

3.	(a)	With the aid of diagrams, explain the following faults with reference to electrical circuits.				
		(i)	Open eineuit.			
		(i) (ii)	open circuit; short circuit.			
		(11)	SHORT CIFCUIT.	(4 marks)		
	(b)	Distin	nguish between operation and maintenance manuals as refers to ele	ectrical		
		mach	ines.	(4 marks)		
	(c)	Expla	in the following maintenance principles:			
		(i)	scheduled maintenance;			
		(ii)	preventive maintenance;			
		(iii)	corrective maintenance.			
D (open		()	Corrective maintenance.	(10 marks)		
5	(d)	Expla	in how faults can be identified on a PCB (Printed Circuit Board)	(2 marks)		
A.	(a)	(i)	Define the following terms with reference to systems:			
			I. Reliability; - Modify of a compound to a cycle ?	a parterio è spess		
			n. landic.			
		(ii)	Explain four causes of failure.	(61)		
15			- quality	(6 marks)		
	(b)	Expla	in the following reliability indices:			
		(i)	Mean time between failure;	cars oronalis is g		
		(ii)	Mean time to failure;			
		(iii)	Maintainability; - to the Machine white the Manage of Ma			
		(iv)	AVAIIADIIITV			
7.7			Prince of Economic of Economic of the Composition of the	(8 marks)		
O's halm	(c)	With t	the aid of a diagram, explain failure periods.	(4 marks)		
, Joseph , San Jan Jan Jan Jan Jan Jan Jan Jan Jan J	(d)	The Mof a si	ITBF of a certain equipment is 500-hours. Determine the probabil milar equipment in:	ity of failure		
		(i)	100 - hours of life; $\Omega = e^{-t/m}$			
		(ii)	1000 - hours of life.			
		(11)	1000 - nouis of file.	(2 marks)		
			- R = e ^{-ym}			
1000			20			
12/20			1501			
	° ° °	9	7.3°			
	50	S	1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600 - 1600	(
3301 18	}	D7 "	3 ⁴ / _{2 = 100} 10	150)		
1 1 1 m		5 8	1/2 e 300 1/4 De	26/201		
02/		2 1	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4			
\$ 75 2521/1	05	S	15/2			
2601/1			3	Turn over		
2001/1		50 X 20	Kr. " 150, "50.			
		10,50	20x 150 20/2016/1 301			

SECTION B

Answer any TWO questions from this section.

- 5. (a) (i) Define the following terms:
 - Proton; 7 It is positive Electrons in an atom. I.
 - Neutron .- It is Tregeric Electrons in an estom II.
 - (ii) Distinguish between excited and ionized atoms.

(6 marks)

With the aid of a diagram, explain the principle of operation of a cathode ray (b) osalloscope. (14 marks)



(4 marks)

Distinguish between intrinsic and extrinsic semiconductor. (4 ma

With the aid of a labelled circuit diagrams, explain forward and reverse bias of a PN (b) function diode.

(16 marks)

(a)

With the aid of symbols differentiate between PNP and NPN transistors:

(6 marks)


- (b) With aid of a circuit diagram, derive currents relationship in a common emitter PNP configuration. 1c = 1 = 1e = 0/18 (12 marks)
- 1E = 1e+1B The following currents were obtained in a transistor connected in Common Base (CB) (c) configuration:




 $I_{\rm F} = 2$ mA, $I_{\rm R} = 20$ mA. Determine the values of α and $I_{\rm C}$


(2 marks)














- 8. (a) State four advantages of FETS (Field Effect Transistors).
 - (b) Figure 1 shows a common drain JFET Amplifier. If $r_d = 100k\Omega$, $g_m = 300\mu s$ and $R_L = 10k\Omega$, determine:
 - (i) voltage gain; = 3m = 8km (1-vcs)
 - (ii) output resistance. We are the grant selection (4 marks)



- (c) With the aid of a labelled diagram, explain the operation of a $\overline{1}$ fitter. (5 marks)
- (d) With the aid of a labelled diagram, explain the operation of a Zener diode shunt regulator and derive the expression for the regulator resistance. (7 marks)

